



8554 Hayden PL · Culver City, CA 90232 · 800.291.2828 · Fax 310.845.1538

MATERIAL SAFETY DATA SHEET

MSDS contrastpm® 15% Whitening Gel

TRADE NAME: contrastpm® Whitening Gel.

DATE REVISED: July 24, 2009

MANUFACTURER:

8554 Hayden Pl.
Culver City, CA 90232
Information Phone Number: (800)291.28.28
Fax: (310) 845.1538

SECTION I

HAZARDOUS INGREDIENTS

Chemicals	CAS	%	TLV
Urea Hydrogen Peroxide	124-43-6	15	1.4mg/m3
Tris Amino		2.5	0.1mg/m3
EDTA		.03	1.4mg/m3

SECTION II – PHYSICAL & CHEMICAL CHARACTERISTICS

- . Boiling Point: ND
- . Vapor Pressure (mm Hg): ND
- . Vapor Density (Air = 1): ND
- . Specific Gravity (H2O=1): ND
- . Appearance and Odor: Clear gel, Peppermint odor
- . Percent Volatile by Volume (%): ND
- . Evaporation Rate: ND
- . Solubility in Water: Partially soluble

SECTION III – FIRE AND EXPLOSION DATA

- . Flash Point: ND
- . Flammable Limits: ND
- . Extinguishing Media: ND
- . Special Fire Fighting Procedures: None
- . Unusual Fire & Explosion Hazards: None



8554 Hayden PL · Culver City, CA 90232 · 800.291.2828 · Fax 310.845.1538

SECTION IV – HEALTH HAZARD DATA

- . Threshold Limit Value: 10mg/m³
- . Effects of Overexposure: Eye Contact – Irritation.
- . Emergency and First Aid Procedures:
 - . Eyes – Flush eyes with water. Seek medical attention.
 - . Inhalation – Remove to fresh air. Seek medical attention.
 - . Ingestion – Seek medical attention.

SECTION V - REACTIVITY DATA

Stability: Stable

Conditions to avoid: Heat & Moisture

Incompatibility (Materials to avoid): None

Hazardous Decomposition: Not Applicable

Hazardous Polymerization: Will not occur.

SECTION VI - SPILL OR DISPOSAL PROCEDURES

Steps to be taken in case material is released or spilled:

Wipe up with cloth or paper towel.

Waste Disposal Method

In accordance with local, states, and federal regulations.

SECTION VII - SPECIAL PROTECTION INFORMATION

Respiratory Protection: Not Required

Ventilation: Normal air conditioning

Protective Gloves: Recommended for use when handling the gel

Eye Protection: Wear safety glasses/goggles.

Other Protection Equipment: Gloves & long sleeved lab coat. Face shield.

SECTION VIII - SPECIAL PRECAUTIONS

Precautions to be taken in handling and storage:

Avoid heat and moisture.

Other precautions:

Clean up spills as floor may become slippery. Use good housekeeping practices.