



MATERIAL SAFETY DATA SHEET

MSDS contrastpm® 10% Whitening Gel

TRADE NAME: contrastpm® Whitening Gel.

DATE REVISED: August 17th, 2006

MANUFACTURER:

American Medical Technologies, Inc.
8655 Bear Lane
Corpus Christi, TX 78405
Information Phone Number: (800) 556-7606
Emergency Phone Number: (361) 289-1145
Fax: (361) 289.5554

SECTION I

HAZARDOUS INGREDIENTS

Chemicals	CAS	%	TLV
Urea Hydrogen Peroxide	124-43-6	10	1.4mg/m3
Tris Amino		2.5	0.1mg/m3
EDTA		.03	1.4mg/m3

SECTION II – PHYSICAL & CHEMICAL CHARACTERISTICS

- Boiling Point: ND
- Vapor Pressure (mm Hg): ND
- Vapor Density (Air = 1): ND
- Specific Gravity (H₂O=1): ND
- Appearance and Odor: Clear gel, Peppermint odor
- Percent Volatile by Volume (%): ND
- Evaporation Rate: ND
- Solubility in Water: Not soluble

SECTION III – FIRE AND EXPLOSION DATA

- Flash Point: ND
- Flammable Limits: ND
- Extinguishing Media: ND
- Special Fire Fighting Procedures: None
- Unusual Fire & Explosion Hazards: None

SECTION IV – HEALTH HAZARD DATA

- Threshold Limit Value: 10mg/m³
- Effects of Overexposure: Eye Contact – Irritation.
- Emergency and First Aid Procedures:
- Eyes – Flush eyes with water. Seek medical attention.
- Inhalation – Remove to fresh air. Seek medical attention.
- Ingestion – Seek medical attention.

SECTION V - REACTIVITY DATA

Stability: Stable

Conditions to avoid: Heat & Moisture

Incompatibility (Materials to avoid): None

Hazardous Decomposition: Not Applicable

Hazardous Polymerization: Will not occur.

SECTION VI - SPILL OR DISPOSAL PROCEDURES

Steps to be taken in case material is released or spilled:

Wipe up with cloth or paper towel.

Waste Disposal Method

In accordance with local, states, and federal regulations.

SECTION VII - SPECIAL PROTECTION INFORMATION

Respiratory Protection: Not Required

Ventilation: Normal air conditioning

Protective Gloves: Recommended for use when handling the gel

Eye Protection: Wear safety glasses/goggles.

Other Protection Equipment: Gloves & long sleeved lab coat. Face shield.

SECTION VIII - SPECIAL PRECAUTIONS

Precautions to be taken in handling and storage:

Avoid heat and moisture.

Other precautions:

Clean up spills as floor may become slippery. Use good housekeeping practices.